



This drawing, specifications, and concepts contained here in are the sole property of Red Barn Machine, and may not be reproduced or used in any fashion without the prior written permission of Red Barn Machine.


REVISIONS				
REV	DESCRIPTION	DATE	INITIAL	APPROVED
A	CH'D Ø1.875 TO STOCK REFERENCE DIMENSION. CH'D TOOL NAME WAS REMOVER, BEARING AND BUSHING IS DRIVER, BRG. REMOVAL, FREEWHEELING ASSY.	12/18/13	RJC	GE



#### NOTES

1. TEST PIECE RC. 28.
2. ALSO KNOWN AS 'BAR'.
3. MASTER CROSS REF. DATA # 5120-01-195-0706.

ASSY QTY	ASSY #	B/O	PART #	UNIT QTY	DESCRIPTION	MATERIAL	B/O INFORMATION OR SPECIFICATIONS
			-101	1	REMOVER	4140 Q&T	Ø1.875 x 1-3/4
SCALE	1 : 1	DATE	9-11-09	SHEET	1 of 1		

 RED BARN MACHINE	
TITLE DRIVER, BRG. REMOVAL, FREEWHEELING ASSY.	
DWG NO. RB T103331-101	REV A
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ON: DECIMALS .XXX ± .005 .XX ± .01 .X ± .1	DRAWN BY: PERRITT APPROVED <i>D Weil</i> HEAT TREAT FINISH BLACK OXIDE USED ON MODEL BELL 0H-58D KIOWA WARRIOR
UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	